

GOVT. SR. SEC. SCHOOL SADWAN

TEH. NURPUR, DISTT. KANGRA (H.P.)



SCHOOL DISASTER MANAGEMENT PLAN

SESSION - 2013-14

**PROJECT UNDER
STATE DISASTER MANAGEMENT AUTHORITY**

INDEX

S.N	Contents	Page no
1	Cover page	1
2	Sec-1 (INTRODUCTION)	3-7
3	School profile	4
4	Detail of school profile	5
5	School location	6
6	Objectives of School Disaster Management Plan	7
7	Sec-2 (HAZARDS RISKS And VULNERABILITY)	8-13
8	Preparation of team to find both Structural and Non-Structural Defects	9
9	Building detail	10
10	Dangers threatening the school	11
11	Structural and Non-Structural Defects	12
12	Sec-3 (PREPAREDNESS)	14-24
13	Constitution of SDMC and roles, responsibilities of teachers and students	15
14	Detail of drills	18
15	Equipment and tools	23
16	Awareness material	24
17	Sec-4(RESPONSE)	25-28
18	List of sign boards installed	26
19	List of students with special needs	29
20	Sec-5(MITIGATION)	30-35
21	Other Non-Structural Defects	31
22	Preventions And Safety measures at Chemistry Lab	32
23	Fire Safety	33
24	Electric Safety	34
25	Other documents Signature of Principal	35

SECTION -1

INTRODUCTION

1. SCHOOL PROFILE
2. AIM AND OBJECTIVE OF THE PLAN
3. GEOGRAPHICAL LOCATION OF THE SCHOOL



SDMP SESSION 2013-2014



Prepared under Government of India – UNDP DRR Programme (2013)

SCHOOL PROFILE

Government Senior Secondary School SADWAN Tehsil Nurpur Distt. Kangra H.P 176202

S.N	Particulars	detail	
1	Name of School	Government Senior Secondary School SADWAN tehsil Nurpur Distt. Kangra H.P 176202	
2	Name of Principal	Sh. Bachitter Singh	
3	Name of In-charge	Bhartendu	Lect. In Chemistry
4	Name of In-charge (Asso.)	Miss Ruchi	Lect. In Biology
5	Name of In-charge (Asso.)	Miss Sanjogita	Lect. In Sanskrit
6	Date of Execution of DMP	1 st April 2013	
7	Date of recommendations	10 th April 2013	
8	Date of Implementation of DMP	15 th April 2013	
9	Date of 1 st Revision	Tentative -- After 6 months	
10	Date of 2 nd Revision(Proposed)	Tentative -- After 12 months	


Detail of School Profile

1. Name of School : **GSSS Sadwan Tehsil Nurpur Distt. Kangra H.P**
2. Code of School :
3. Contact Numbers: 01893-234120
4. Number of Teachers : Male 12 Female 17.
5. Number of Students: Male 280 Female 300
6. Number of Differentially able students Male 02 Female 03
7. Date of construction of School Building: **year of construction 1989**
8. Number of buildings in the school compound: 03
9. Number of classrooms : 17
- Number of Chemistry Laboratory : 1
- Number of Physics Laboratory : 1
- Number of Biology Laboratory : 1
- Number of Junior Science Lab : 1
11. Number of Floors : 2
12. Number of stair cases : 3
13. Do you have a kitchen? Yes/No : Yes
Kitchen with Cooking gas connection as well as open fire Kitchen
14. Do you have toilets separate for : Boys – Yes Girls – Yes
15. Number of drinking water points : 07
16. Playground size and open area : available approx. 100X75 M
17. Fire extinguishers installed : Yes
- Number of fire extinguishers : 05
- Date hen last checked : 1st April 2013
18. Number of Sand buckets : 05
19. Evacuation Drill organized : Yes
Last date when drill conducted and number of student who participated : 01/05/2013

SIGNATURE OF PRINCIPAL

Location and Map of GSSS Sadwan

Location and co-ordinates
32-18 N to 32-3 N & 75-54 E to 75-9 E
Sub-Division Nurpur 10 KM



Objectives of School Disaster Management Plan

Keeping in view of both Natural and Man Made Disaster the School Disaster management plan is prepared under the guidance of HP State Disaster management Authority (SDMA) and H.P Department of Education.

The School Disaster management committee is framed under the chairmanship of Principal along with President SMC and Master Trainers of School. The Committee is authorized to find out all the risks during any type of Disasters. They are also asked to find out all risks as well as their remedies both at structural level and Non-Structural level.

The Plan was prepared on 1st April 2013, the In-Charges find out all the risks as well as all Structural and Non Structural Risks of the School.

Finally the plan is implemented on 15th April 2013. The evacuation routes of whole campus prepared, Mock-Drills for earthquakes and fire safety were demonstrated and performed again and again, all SDM committees were formed and their tasks assigned to them and report on structural and Non-Structural hazards is submitted to the Principal Office.

SECTION-2

Hazards Risks and Vulnerability Assessment

1. Preparation of team to find both Structural and Non-Structural Defects
 2. Preparation of School map and open area
 3. Dangers threatening to the school
 4. Structural And Non Structural Defects

Preparation of team to find both Structural and Non-Structural Defects

A team of three teachers under the chairman-ship of Principal prepared to find all the Structural and Non-Structural Defects of the school campus, Bhartendu (Lecturer in Chemistry), Miss Ruchi (Lecturer in Biology) and Miss Sanjogita (Lecturer in Sanskrit), closely visited all the rooms of School and submitted their report to the Principal Sh. Bachitter Singh for further modification and rectification.

On the recommendation of Principal necessary Non-Structural modifications and retrofitting were done and where ever it was necessary the almirahs were dislocated.

BUILDING WISE DETAIL

BLOCK	BUILDING NAME	TOTAL NO. OF ROOMS	TOTAL NO. ONLY CLASS ROOMS	AGE GROUP OF STUDENTS	TYPE OF ROOF CONSTRUCTION	AGE OF BUILDING	REMARK
BLOCK-I	ADMINISTRATIVE BLOCK	06	NIL	N.A	RCC	15 Yrs.	IN USE
BLOCK-II	STAFF ROOM & LIBRARY	04	01	14-16	RCC	20 Yrs.	ABANDONED
BLOCK-III	ACADEMIC BLOCK - GROUND FLOOR	10	08	12-14	RCC	10 Yrs.	IN USE
BLOCK-IV	ACADEMIC BLOCK – FIRST FLOOR	10	08	14-16	RCC	10 Yrs.	IN USE
BLOCK-V	LABORATORIES	01	NIL	14-16	RCC	10 Yrs.	IN USE

DETAILS OF OPEN SPACE/GROUND

S.N	TYPE OF OPEN SPACE	APPROX. SIZE [LXB]	ACCESSIBILITY FROM THE ROAD (YES/NO)	DISTANCE FROM THE MAIN ROAD
1	PLAY GROUND WITH SWING	Approx. 100X100 M	Yes	15 METERS
2	CRICKET, FOOT-BALL FIELDS	Approx. 100X100 M	Yes	15 METERS
3	BASKET BALL COURT	Approx. 60X60 M	Yes	50 METERS
4	ASSEMBLY GROUND	Approx. 50X50 M	Yes	25 METERS
5	BOLLYBALL COURT	Approx. 30X30 M	Yes	50 METERS
5	BADMINTION COURT	Approx. 25X25 M	Yes	30 METERS

Dangers threatening the school

Natural Disasters

1. Earthquakes : School is located in Distt. Kangra which is in Zone-V
2. Flash Floods & Storms: School is located in the foothills of Kangra Valley
where excessive rains and storms are more frequent
3. Forest Fire : Thick forest of Pines and other trees is in the vicinity of School.

Accidents

1. Road Accident : The School is situated on the Nurpur-Chamba State Highway facing huge traffic of vehicles and tourists.
2. Fire : MDM Kitchen, Chemistry Laboratory is present in the School Campus.
3. Structural Damages : Block-II is declared unsafe, hence is vulnerable in Nature.

Structural and Non-Structural Defects

Name of the Block	Room No.	Name of Room	Type of Roof	Structural Defect	Non-Structural Defect	Remarks
Block-I Administrative Building	Room-1	Principal Office	RCC	Damped Wall	Hanging Photo Frames Mirror Hanging Board Almirah Hanging wires	Removed and some are fitted on the walls
	Room-2	Office-Store	RCC	Dampness	File Rack and Cupboard Lose Wiring and Open MainSwitch	
	Room-3	Principal's Room	RCC	Nil	Hanging Photo Frames Mirror Hanging Board Almirah Hanging wires	Removed and some are fitted on the walls
	Room-4	Science Laboratory	RCC	Damped Roof	Drawing Boards, Models and Practical Files On Almirahs and Cupboard,	removed
	Room-5	Kitchen Store	RCC	Nil	Location of Container and Kitchen Articles not Proper Loose wiring	arranged
	Room-6	Kitchen	RCC	Nil	Location of Stove and Gas pipe improper	
Block-II Library and Staff Room	Room -1	Staff Room cum Library	RCC	Damped Roof Damped Walls Old building	Loose wiring ,disordered almirahs and trunk	Abandoned Declared Unsafe
	Room-2	Classroom	RCC	Damped Roof Damped Walls Old building	Division of room by wooden board and single entry and exit only	Abandoned Declared Unsafe
	Room-3	Old Class Room	RCC	Damped Roof Damped Walls Old building	Room not in use.	Abandoned Declared Unsafe
Block-III Ground Floor Academic Building	Room-1	Sports Room	RCC	No	Tv, Photo frames, trunk, huge heap of old Practical notebooks	Removed and some are fitted on the walls
	Room-2	Multimedia Lab.	RCC	No	Single entry , chairs not arranged	Second door opened
	Room-3	Class Room	RCC	No	Single entry. Loose wiring, Fan hanging	

	Room-4	Class Room	RCC	No	Single entry. Loose wiring, Fan hanging	
	Room-5	Class Room	RCC	No	Single entry. Loose wiring, Fan hanging	
	Room-6	Class Room	RCC	No		
	Room-7	Class Room	RCC	No		
	Room-8	Toilets	RCC	No		
Block-IV First Floor Academic Building	Room-1	I.T Lab	RCC	No	Single entry.	Second door opened
	Room-2	Class Room	RCC	No	Single entry. Loose wiring,	
	Room-3	Class Room	RCC	No	nil	
	Room-4	Class Room	RCC	No	Nil	
	Room-5	Examination Hall	RCC	No	Loose wiring,	
	Room-6	Class Room	RCC	No	Loose wiring,	
	Room-7	Class Room	RCC	No	Nil	
	Room-8	Physics Lab	RCC	Dampness in walls	Position Almirahs and working tables is not proper.	
		Stairs	RCC	No	Nil	

Name of the Block	Room No.	Name of Room	Type of Roof	Structural Defect	Non-Structural Defect	Remarks
Block-V	Room-1	Biology Lab	RCC	Nil	Nil	New building
	Room-2	Chemistry Lab	RCC	Nil	Nil	

SECTION -3

PREPAREDNESS

1. Constitution of SDMC and roles, responsibilities of teachers and students
 2. Awareness materials and campaigning
 3. Detail of drills
 4. Strength of Drills and recommendations
 5. Available Resources

DETAILS OF THE TEAM MEMBERS

A. SCHOOL FIRE MANAGEMENT COMMITTEE

S.N	NAME OF PERSON	DESIGNATION	CONTACT NO.	Email
1	Sh. Bachitter Singh	Principal	9418452817	
2	Sh. Prem Sager	Vice-Principal	94188-64753	
3	Smt. Naveen	Lecturer	94180-66125	
4	Sh. Budhi Singh	Shastri	94183-80385	
5	Sh. Ashok Kumar	L.A	8894220944	
6	Sh. Ravinder	TGT Arts		
7	Sh. Ashok Kumar	President SMC	9805955865	
8	Sher Singh	Student	10+2	
9	Mamta	Student	10+2	

B. AWARENESS CAMPAIGN TEAM

S.N	NAME OF PERSON	DESIGNATION	CONTACT NO.	Email
1	Bhartendu	Lecturer	9418122083	bhartendu_198@yahoo.co.in
2	Miss Ruchi	Lecturer	94590-94386	
3	Miss Sanjogita	Lecturer	94185-64458	
4	Sh. Sandeep Sharma	Lecturer	9418497602	
5	Sh. Ajay Dhiman	Lecturer	94181-65381	
6	Vishwakirti	Student	10+2	
7	Pallavi	Student	10+2	

C. FIRE ALARM TEAM

S.N	NAME OF PERSON	DESIGNATION	CONTACT NO.	Email
1	Sh. Varinder Singh	D.P.E	9459058799	
2	Sh. Budhi Singh	Shastri	94183-80385	
3	Sh. Ravinder	L.A	9805382474	
4	Sh. Ashok	L.A	8894220944	
5	Rishiwar	Student	10+2	
6	Abhishek	Student	10+2	

D. EVACUATION TEAM

S.N	NAME OF PERSON	DESIGNATION	CONTACT NO.	Email	
1	Bhartendu	Lecturer	9418122083		
2	Sh. Ajay Dhiman	Lecturer	94181-65381		
3	Sh. Sandeep Sharma	Lecturer	9418497602		
4	Sh. Varinder Singh	D.P.E	9459058799		
5	Miss Ruchi	Lecturer	94590-94386		
6	Mohit	8 Akshey	Student	10+2	
7	chandan	9 Shubham	Student	10+2	

E. SEARCH AND RESCUE TEAM

S.N	NAME OF PERSON			DESIGNATION		CONTACT NO.	Email
1	Sh. Prem Sager			Lecturer		94188-64753	
2	Sh. Rajeev Gupta			Lecturer		9418092155	
3	Bhartendu			Lecturer		9418122083	
4	Sh. Ajay Dhiman			Lecturer		94181-65381	
5	Sh. Sandeep Sharma			Lecturer		9418497602	
6	Smt. Anita			Lecturer		94184-64172	
7	Miss Jyoti			TGT (N/M)		9459072489	
8	Amit	10	Swarna	Student	10+2		
9	Gourav	11	Pallavi	Student	10+2		

F. FIRE FIGHTING TEAM

S.N	NAME OF PERSON			DESIGNATION		CONTACT NO.	Email
1	Sh. Varinder Singh			D.P.E		9459058799	
2	Sh. Rajeev Gupta			Lecturer		9418092155	
3	Sh. Ravinder			L.A		9805382474	
4	Sh. Ashok			L.A		8894220944	
5	Sh. Budhi Singh			Shastri		94183-80385	
6	Arti Devi			Student	10+2		
7	Avinash			Student	10+2		

G. FIRST -AID TEAM

S.N	NAME OF PERSON			DESIGNATION		CONTACT NO.	Email
1	Bhartendu			Lecturer		9418122083	
2	Miss Ruchi			Lecturer		94590-94386	
3	Smt. Rishu			Lecturer		8679252800	
4	Miss. Sanjogita			Lecturer		94185-64458	
5	Smt. Saroj			TGT		09417818643	
6	Smt. Munna			Lecturer		9459758442	
7	Neha	9	Gaurav	Student	10+2		
8	Sahil	10	Mamta	Student	10+2		

H. SITE SAFETY TEAM

S.N	NAME OF PERSON			DESIGNATION		CONTACT NO.	Email
1	Sh. Sandeep Sharma			Lecturer		9418497602	
2	Mr. Naresh			Peon			
4	Sh. Gandhi Ram			Chowkidar			
5	Sh. Ravinder			L.A		9805382474	

I. TRANSPORTION MANAGEMENT TEAM

S.N	NAME OF PERSON	DESIGNATION	CONTACT NO.	Email
1	Sh. Bachitter Singh	Principal	9418452817	
2	Sh.Prem Sager	Lecturer	94188-64753	
3	Sh. Tilak Raj	Superintendent	98166-41733	
4	Sh. Sandeep	Sr. Asstt.	9418461364	
5	Smt. Anita	Lecturer	94184-64172	

J. MEDIA MANAGEMENT TEAM

S.N	NAME OF PERSON	DESIGNATION	CONTACT NO.	Email
1	Sh. Tilak Raj	Superintendent	98166-41733	
2	Sh. Sandeep	Sr. Asstt.	9418461364	
3	Sh. Prem Sager	Lecturer	94188-64753	
4	Sh. Budhi Singh	President SMC	94183-80385	
5	Sh. Anil Choudhary	IT Teacher	98572-71021	

DETAILS OF THE MOCK DRILL

S.N	NAME OF DRILL	DATE & TIME	NO. OF PARTICIPENTS	REMARKS
1	FIRE EVACUATION DRILL	16 th April 2013 9.00 AM	100	Proposed every Monday
2	DROP COVER HOLD DRILL	20 th April 2013 9.00 AM	100	Proposed every Friday
3	SAFETY CONSIDERATION DRILL	22 nd April 2013	10	Proposed 1 st Wednesday every Month
4	ANY OTHER TYPE OF DRILL : FIRST AID DRILL	24 th April 2013	25	Proposed 1 st Thursday every Month

FIRE & EVACUATION DRILL REPORTING FORMAT

S.N	CONTENT	INFORMATION			
1	NAME OF THE SCHOOL	GOVERNMENT SENIOR SECONDARY SCHOOL SADWAN			
2	NAME OF THE PRINCIPAL	SH. BICHITTER SINGH			
3	FULL ADDRESS	GSSS SADWAN TEHSIL NURPUR DISTT. KANGRA H.P 76202			
4	CONTACT DETAIL	LANDLINE NO.	01893-234120	MOBILE NO.	9418452817
5	OWNED BY	GOVERNMENT INSTITUTION			
6	MAINTAINED BY	DEPARTMENT OF EDUCATION HP GOVT.			
7	TOTAL NUMBER OF STAFF MEMBERS	29			
8	TOTAL NUMBER OF STUDENTS	550			
9	TOTAL NUMBER OF CLASSROOMS	17			
10	TOTAL NUMBER OF LABORATORIES	04			
11	OFFICE ROOMS	02			
12	KITCHEN	01			
13	STOORS	01			
14	TOTAL NUMBER OF TOILETS	04 SEPARATE FOR BOYS & GIRLS			

STRENGTHS OF DRILLS

Every member of Team and Students are taking full interest as well are actively participating in the Drills.

WEAKNESSES OF DRILLS

1. Small Children's participation is still awaited and they take more time to learn new things and tactics .


Recommendation /Suggestions For Further improvement

1. Parent's participation along with the school is recommended by the members.
2. Expert advice and more First Aid equipment are required for better consideration.

PHOTOGRAPH SHOWING MOCK DRILL



GOVT. SENIOR SECONDARY SCHOOL SADWAN, TEH. NURPUR, DISTT. KANGRA (H.P.)



Available Resources

Equipment and tools

S.N	Name of Article	Availability	Quantity	Weather working/out of order	Need Repair/or not	remarks
1	First Aid Box	Available	1	-	-	All aids purchased new
2	Fire Extinguishers	Available	4	working	no	Expiry date May. 2014
3	Sand Buckets	Available	4	-	-	filled
4	Ladder	Available	1	-	no	new
5	Television	Available	1	working	no	-
6	Telephone	Available	2	working	no	-
7	Sign Boards	Available	50	-	-	New installed
8	Evacuation Maps	Available	2	-	-	New installed
9	Loud Speakers	Available	1	working	-	-
10	Battery	Available	1	working	-	-
11	Torch	Available	1	working	-	-
12	Ropes	Available	4	-	-	new
13	Bamboo Poles	Available	10	-	-	sufficient
14	Alarm Bell/siren		1	-	-	Order Placed

Awareness material

S.N	Awareness Material	Displayed	Distributed	Remarks
1	Pamphlets	Displayed on Notice Board	Distributed	Positive effect
2	Pictures of Earthquakes	Displayed on Notice Board	Distributed	Positive effect
3	Safety tips	Displayed on Notice Board	Distributed	Positive effect
4	Morning assembly Lectures	Delivered periodically	-	Positive effect
5	Videos	Shown eventually	-	Positive effect

SECTION -4

Responses

1. Installation of evacuation routs and maps at various levels
2. Emergency numbers
3. Special arrangement of students with special needs

All the routes for evacuation during the Fire and Earthquake were prepared and routes installed on walls

List of sign boards installed

S.N	Name of Board	Installed/Not Installed	Number	Remarks
1	Laboratory	Installed	07	
2	Principal rooms	Installed	02	
3	Room wise	Installed	10	
4	Fire Extinguishers	Installed	05	
5	Water Tanks	Installed	02	
6	Toilets	Installed	02	
7	Emergency Cont.	Installed	02	
8	Offices	Installed	02	
9	Kitchen	Installed	02	
10	Don't Go Rash	Installed	02	
11	Electric Main switches	Installed	02	
12	Evacuation Maps	Installed	03	
12	Others	Installed	09	
	Total	Installed	50	

ELECTRIC MAIN SWITCH
खतरा

EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

SCIENCE LABORATORY

EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

ECO CLUB GARDEN AMALTAAS
GOVT. SR. SEC. SCHOOL SADWAN
EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

SPORTS ROOM

EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

KITCHEN SHED
रसोई घर

EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

STORE ROOM
गोदाम कक्ष

EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

DON'T GO RASH
भगदड़ न मचाएं

EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

MULTIMEDIA LABORATORY


EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

DRINKING WATER TANK
पीने का पानी

EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan


VERMICOMPOST SHED

EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan


TOILETS

EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

EXIT
यहाँ से निकले

EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan


TOILETS

EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

**CHEMISTRY
LABORATORY**



EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

**PHYSICS
LABORATORY**



EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

PRINCIPAL ROOM
प्रधानाचार्य कक्ष



EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

**BIOLOGY
LABORATORY**



EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

**WATER
COOLER**



EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

**SCHOOL
OFFICE**
कार्यालय



EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

EXIT
यहाँ से निकले



EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

EXIT
यहाँ से निकले



EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

FIRE
अग्निशमन यंत्र



EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

I.T. LAB



EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

FIRE
अग्निशमन यंत्र



EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

**EMERGENCY
CONTACT NO.**

1. FIRE	-	101
2. POLICE	-	100
3. AMBULANCE	-	108
4. CHILD HELPLINE	-	1098
5. POLICE STATION	-	220028
6. HOSPITAL	-	220036
7. DSP OFFICE	-	220065
8. SDM OFFICE	-	220024

EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

MAIN ENTRANCE
मुख्य द्वार



EARTHQUAKE EVACUATION ROUTE School Disaster Management Plan

List of students with special needs

A class wise list of students with special needs prepared and informed to all the teams for their special attention.

S.N	Class	Boys W.S.P	Girls W.S.P	Total Students W.S.P
1	6 th	Nil	Nil	Nil
2	7 th	Nil	Nil	Nil
3	8 th	Nil	Nil	Nil
4	9 th A	Nil	Neha	01
5	9 th B	Nil	Nil	Nil
6	10 th A	Nil	Sultana bibi	01
7	10 th B	Nil	Shilpa	01
8	10+1 Arts	Rahul	Nil	01
9	10+1 Science	Nil	Nil	Nil
10	10+2 Arts	Nil	Nil	Nil
11	10+2 Science	Nil	Nil	Nil
	Total	01	03	04

SECTION -5

MITIGATION MEASURES

1. Non-Structural Defects
2. Preventions And Safety measures at Chemistry Lab
 3. Fire Safety
 4. Electric Safety

Other Non-Structural Defects

S.N	Name of Room	Non Strc. Defect	removed	Retrofitted	Problem Cleared/Not Cleared
1	Principal's Room	Trophy, Honour Board	Fixed	Fitted	Cleared
2	Corridors	Blocked Passages	Almirahs Displaced	-	Cleared
3	Chemistry Lab	Chemicals and Burners	Placed in Almirahs	-	Cleared
4	Parking	Hindrance during evacuation	displaced	-	Cleared
5	Class Room Entrances	Single entry, second door closed	Second door opened	-	Cleared
6	Electric Fan & Bulbs Fittings	Not inspected from safety point of view	Inspected and fixed	fixed	Cleared
7	Kitchen shed	Fire Extinguisher	Fire extinguisher installed	-	Cleared

Preventions And Safety measures at Chemistry Lab

S.N	Problem	Solution	Problem Cleared/Not Cleared
1	Used & Unused Chemicals	Proper Disposable	Pitch Made to dispose them
2	Storage of Chemicals	Placed in almirahs and below the Tables	cleared
3	Proper position of Fire Safety	Fire extinguisher installed	Cleared
4	Glass wares	Placed safely in the Almirah in their covers	Cleared
5	Sand-Buckets	Placed in and outside the lab	Cleared
6	Space availability	Small room	Informed to SDMC for spacious room

Fire Safety

Fire extinguishers and sand buckets were placed wherever they are necessary. Date of installation as well their type and date of expiry were noted and contact numbers of supplier providing refills properly noted.

Fire safety teams prepared they were explained about the mechanism of fire and were explained how to use fire extinguishers, sand buckets and Fire safety drills were taught.

First Aid Team were acquainted with the fire wounds and were explained how to treat fire burns.

The help of Health Department was taken in this regard.

Fire Brigade numbers were noted and displayed on the emergency nos.

Electric Safety

SDMC inspected whole building and blocks of school and prepared a list of electric hazards and also suggested the measures, at some places the wiring was open and fan hangings were not proper. With the help of electrician all the loose wire were repaired and fan hangings were checked. Main switches were and fuse with kit-kat are installed.


Sign board with danger signals also placed to aware the students.

ENCLOSURES (Tick all the enclosed ones with nos.)

TYPE OF ITEM	NOs.
PHOTOGRAPHS	6 pages
NEWSPAPERCLIPPINGS	01
CUTOUTS	02
ANY OTHER	School maps/emergency no. /routs = 05

NAME OF ORGANISING AUTHORITY	Sh. BACHITTER SINGH PRINCIPAL GSSS SADWAN	
FULL ADDRESS	GSSS SADWAN tehsil Nurpur Distt. Kangra H.P	
SIGNATURE WITH OFFICE SEAL		
Date/Place	10/05/2013 GSSS Sadwan	

PHOTOGRAPH SHOWING INSTALLATION OF EVACUATION ROUTES





BLOCK - V [CHEMISTRY & BIOLOGY LAB.]



BADMINTON COURT

**GOVERNMENT SENIOR SECONDARY SCHOOL SADWAN TEHSIL NURPUR
DISTT. KANGRA H.P 176202**

CERTIFICATE

It is certified that this project report if prepared by **Sh. Bhartendu Lect. In Chemistry** and In-Charge School Disaster Management Committee (SDMC) of GSSS Sadwan, A project under State Disaster management Authority (SDMN) Himachal Pradesh Government Shimla.

All Structural and non-structural Hazards are detected, and remedial measures have been taken after the recommendation of SDMC with the help of Members **Miss. Ruchi (Lect. Biology) and Miss Sanjogita (Lect. Sanskrit)** . Sign Boards installed and evacuation map pasted on the walls and equipment are prepared during and after the unfortunate circumstances.

PRINCIPAL

CUM CHAIRMAN SDMC

GSSS SADWAN

10/05/2013